RFA


RITTNER FRENCH ASSOCIATES

Rittner French Associates / Rittner Products, Inc.

800-RFA-4-SPEC – www.rittnerfrench.com


Consulting services from Rittner French Associates helps reduce the frustration that goes along with making complex decisions on how to best solve your Hardware Location Challenges.

Typical ADA Locations And Information For Door Hardware



DOJ's ADA Standards for Accessible Design (2010)

Doors: Section 404



+ Note: This diagram is a generalization for ADA mounting. In no way is this a code document. Consult with the Authority Having Jurisdiction for complete code requirements.